

Michael O. Leavitt Governor Ted Stewart Executive Director James W. Carter

Division Director

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340 801-359-3940 (Fax) 801-538-5319 (TDD)

May 26, 1994

Mr. Alan Wilson Senior Reclamation Engineer Hecla Mining Company 6500 Mineral Drive Box C-8000 Coeur d'Alene, Idaho 83814-1931

Re: Supplemental Reclamation Plan Information, Hecla Mining Company, Escalante Silver

Mine, M/021/004, Iron County, Utah

Dear Mr. Wilson:

Please find attached, a copy of the field inspection memorandum that was prepared documenting our recent (May 6, 1994) Board/Division tour of the Escalante mine site. The memorandum outlines the discussions I had with you at the end of the tour, concerning the specific type of supplemental reclamation information requested in our April 25, 1994 letter.

Our April 25th letter requested receipt of the supplemental information by June 6, 1994. Because you have been waiting for a follow up letter, and/or copy of the attached inspection memo before preparing your response, we will extend the timeframe for responding until June 30, 1994.

Thank you for your patience and cooperation in addressing this matter. Please contact me directly should you have remaining questions or concerns in this regard.

Sincerely,

D. Wayne Hedberg

Permit Supervisor

Minerals Regulatory Program

attachment

cc: Low

Lowell Braxton, DOGM

Minerals staff (route)

M021004.sup





DIVISION OF OIL, GAS AND MINING

Governor Ted Stewart Executive Director James W. Carter Division Director

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340 801-359-3940 (Fax) 801-538-5319 (TDD)

May 13, 1994

TO:

Minerals File

FROM:

Travis Jones, Reclamation Hydrologist

D. Wayne Hedberg, Permit Supervisor

RE:

Site Inspection, Hecla Mining Company, Escalante Silver Mine, M/021/004,

Iron County, Utah

Date of Inspection: May 6, 1994 Time of Inspection: 1000-1145 Conditions:

Sunny, windy

Participants:

Board of Oil, Gas and Mining: Alan Wilson--Hecla Mining Company: Arthur Tait, Gina Pack--BLM: James Carter, Lowell Braxton, Wayne

Hedberg, Travis Jones, Tom Mitchell, Ron Daniels, Jan Brown, and

Joelle Burns--DOGM

Purpose of Inspection:

Board Tour; to see the progress of the reclamation of the

mine site and tailings impoundment

Alan Wilson gave us a brief project history and brought us up-to-date on the progress of the reclamation that has transpired to date.

The mine was shutdown, shafts, decline/entries backfilled/sealed, and the pumps pulled from the mine dewatering wells in 1989. The 17 mile canal used for aquifer recharging has been reclaimed. Mr. Wilson told us that some of the onsite milling and processing equipment has been removed and taken to their Grouse Creek mine in Idaho. He indicated that the remaining milling/processing equipment would probably be moved to their Grouse Creek mine or their new Rosebud project located in Nevada. He did not have a definitive timeframe, but thought this would happen gradually over the next 1 1/2 - 2 years. Mr. Wilson indicated the northern most office facility had been sold as part of a 20-acre parcel to Reliant Testing Company. He stated that Hecla may be putting up another 20 acre parcel of mine property for sale in the near future. An old onsite head frame apparently has some historical value and will remain. Photographs were taken of the remaining structures and facilities.



Page 2 Site Inspection M/021/004 May 13, 1994

Next we proceeded to the tailings impoundment. The 10-inch layer of wasterock, comprising the capillary barrier, had been spread over the impoundment. Survey stakes, indicating the depth of subsoil to be placed, were present. Mr. Wilson informed us that a minimum of 18 inches of subsoil would be spread over the impoundment. Some places (nearer the dam) could receive up to four feet of subsoil in order to attain the proper final grade. Scrapers were actively stripping and placing subsoil during our inspection.

We observed a new runoff control ditch being constructed around the perimeter of the impoundment. Mr. Wilson indicated that, to his knowledge, runoff has never flowed in the upper undisturbed area diversion ditch during the life of the impoundment. The new ditch has been sized for an extreme precipitation event, will be riprapped at critical sections, and should be more than adequate to handle all the runoff from the contributing watershed areas.

At the conclusion of the inspection/tour by the Board, Wayne Hedberg asked Alan Wilson to provide the Division with a detailed inventory of the structures/facilities remaining onsite. The list should be cross-referenced to an updated site facilities map which shows the location of remaining structures. Those facilities that no longer exist should be labelled accordingly. A description of Hecla's proposed plans for the remaining facilities, including any plans for the future sale of the properties or equipment, should also be provided. A description of any previous property sale(s) is also necessary. Mr. Hedberg also asked Mr. Wilson to provide a general cost estimate for demolition and reclamation of the remaining surface facilities that presently is not described in the approved reclamation plan. This supplemental information should be formatted to be included as an addendum/amendment to the approved mining and reclamation plan. Mr. Hedberg and Mr. Wilson also discussed the need to arrange their schedules for a future site inspection with the BLM to jointly review the status of completed reclamation activities. The inspection/tour concluded at about 11:45 a.m.

jb cc: Arthur Tait, BLM Alan Wilson, Hecla Lowell Braxton Minerals staff (route) M021004.ins Michael O. Leavitt Governor Ted Stewart **Executive Director** James W. Carter Division Director 801-538-5319 (TDD)

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340 801-359-3940 (Fax)

Date:	May 26, 1994
	Pages Including This Cover Sheet:
TO:	alan Wilson
	Heala mining Co
. 3	6500 Mineral Or Box C 8000
	Coem Velene ID 83814-1931
Phone: (Fax) 1-208-769-4/22	
FROM:	Wayne Healing
	Minerals Reclamation and Development Program
Phone:	(801) 538-5340
FAX:	(801) 359–3940
SUBJECT:	Lite Inspection - Escalante Silver Mine
	m/021/004
REMARKS:	hard copy will be in todays mail.
KBIMICO.	The state of the s
Should	you encounter any problems with this copy, or do not receive all the pages, please call
	The family of th

MN9/61